

Tasks to Complete	Responsible Person	Projected Completion Date	Suggestions	Estimated Cost
<ol style="list-style-type: none">1. Emergency button not accessible on track, no Braille.2. Doors are too heavy in downstairs classrooms.3. Signs have letters in raised Braille, but they are not specific enough and the symbols are not raised.4. Emergency sign had "emergency" in raised Braille, but the specific steps to take during the emergency were not in Braille.5. Soap dispensers not accessible on the first floor bathroom; soap dispensers were too high.			<ol style="list-style-type: none">1. Possible secondary device for blind/ vision impaired individual (for example, a device you could put in your pocket connected to the emergency button on the wall)2. Make doors a lighter weight by changing the weight mechanism of the door.3. Raise symbols on signs and make Braille more specific.4. Raise symbols on signs and make Braille more specific.5. Lower soap dispensers on first floor bathroom.	