BUILDING: HOLT HALL]

Tasks to Complete	Responsible Person	Projected Completion Date	Suggestions	Estimated Cost
Insure that mounted trashcans				
have enough clearance to be				
detectible by a cane.				
Post directional signage				
indicating the location of the				
accessible entrance.				
3. Secure edges of carpets and				
mats.				
4. Replace door knobs with				
handles.				
5. Post Braille signs for all room				
numbers and department offices.				
numbers and department offices.				
6. Install visible and audio				
notification system.				
,				
7. Lower the call buttons in the				
elevator to 42 inches high.				
8. Post Braille numbers in				
elevator and Braille markers on				
each floor.				
O. Emergency intereses in				
Emergency intercom in elevator must have visible				
notification possibility.				
notification possibility.				
10. Post tactile signage for				
accessible bathroom.				

Physical Access [BUILDING: HOLT HALL]

	<u></u>		
10. Modify handles for accessible stall to be opened with a closed fist.			
11. Install grab bars in accessible bathroom stall.			
12. Soap dispenser, hand dryers, and mirror in accessible bathroom needs to be lowered to 40 inches.			
13. Install a cane detectable barrier at drinking fountains.			