

Tasks to Complete	Responsible Person	Projected Completion Date	Suggestions	Estimated Cost
<p>1. Install curb cuts at drives and parking spots.</p> <p>2. Check ramp height at gate 3 to ensure that it is the appropriate ration of 1:12.</p> <p>3. Post directional signage indicating the location of the accessible entrance.</p> <p>4. Replace the door knob with a more accessible handle on the alternate entrance.</p> <p>5. Secure the edges of all carpeting and mats.</p> <p>6. Post high contrast, tactile, and Braille signs indicating room numbers and office names on the latch side of the doors.</p> <p>7. Have an accessible table available in all rooms with a knee space of at least 27 inches high, 30 inches wide, and 19 inches deep.</p> <p>8. Lower a potion of food ordering counters to no more than 36 inches in height.</p>		<p>Completion dates are contingent on funding decisions.</p>	<p>Use in house sign making</p> <p>At each concession area</p>	

<p>9. Post Braille signs to identify stair access.</p> <p>10. Replace inaccessible door knobs to stairwells with a more accessible handle.</p> <p>11. Install non slip surface on stairs.</p> <p>12. Install visible/auditory signal system in elevator.</p> <p>13. Reconfigure restrooms so there is at least one men and one women's restroom accessible to patrons with disabilities. This should include handles operable with a closed fist, sink free space for wheelchair access; soap dispensers, towel dispensers, and mirrors should be no higher than 40 inches.</p> <p>14. Post directional signage indicating the location of the accessible restroom.</p> <p>15. Post indicator signage in both high contrast and Braille for the accessible restroom.</p>				
--	--	--	--	--

16. Lower a drinking fountain to no more than 36 inches in height.				
--	--	--	--	--